

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
DEL,  
1- MAG,  
2 -

Matthew Lowber House  
North Main Street  
Magnolia  
Kent County  
Delaware

DE-182

Documentation: 7 sheets (1975, including site plan, plans, elevations, section)  
4 exterior photos (1982)  
5 interior photos (1982)  
12 data pages (1975)  
1 set of field records (1 notebook, 35 photos)

Jack E. Boucher, Photographer      July, 1982

DE-182-1    SOUTHWEST FRONT

DE-182-2    SOUTHWEST FRONT FROM WEST

DE-182-3    SOUTHWEST FRONT FROM SOUTH

DE-182-4    SOUTHEAST GABLE END, SHOWING DATE IN GLAZED HEADERS

DE-182-5    FIRST FLOOR, SOUTHWEST WALL OF SOUTHEAST ROOM

DE-182-6    FIRST FLOOR, SOUTHEAST ROOM DETAIL OF STENCILED CEILING IN SOUTH CORNER

DE-182-7    FIRST FLOOR, CENTER ROOM, DETAIL OF WINDOW IN SOUTHWEST WALL

DE-182-8    SECOND FLOOR, SOUTHEAST WALL OF SOUTHEAST ROOM

DE-182-9    SECOND FLOOR, SOUTHEAST ROOM, DETAIL OF STENCILED CEILING